

LUSCOMBE AIRPLANE CORPORATION

SERVICE BULLETIN #6

June 1, 1939

REF: Elevator Cables, Models 8 & 8A
Serial Numbers 801 through 940 Incl.

We are very glad to say that our persistent efforts along the line of general improvement, have greatly reduced the necessity of making changes in our airplane.

However, a recent service inspection of a factory owned airplane discovered a frayed elevator cable. The fraying occurred in the vicinity of the pulleys located on bulkhead 3, just aft of the seat. We now think these pulleys should have a greater radius.

All owners of Model 8 and 8A airplanes are advised to inspect their elevator cables and report to us if they see any signs of cable fraying, in which case we shall be glad to furnish you with the cables.

LUSCOMBE AIRPLANE CORPORATION

Engineering Dept.

Retyped March 2, 1960

SILVAIRE AIRCRAFT CO.
P.O. BOX 719
FORT COLLINS, COLORADO

ped